

Checked

This vehicle has been subject to and passed the AA Mechanical Check for used vehicles in the following areas:

- ▶ **Body Exterior Fittings**
- ▶ **Engine Compartment**
- ▶ **Front Suspension, Steering & Underframe**
- ▶ **Exhaust System**
- ▶ **Fuel System**
- ▶ **Road Test**
- ▶ **Interior Fittings**
- ▶ **Electrical & Controls**
- ▶ **Rear Suspension & Underframe**
- ▶ **Transmission**
- ▶ **Brakes**
- ▶ **Wheels & Tyres**

The vehicle with registration number:

PN61HHK

Passed the AA Mechanical Check for Used Vehicles.

Report Number: **AAMC111450**

Date: **27-11-2014**

AA Engineer: **Peter Mackay**

AA MECHANICAL CHECK

Dealer's Name:	Motor Market Ltd	27 Newtown Lane
Report Number:	AAMC111450	Cradley Heath
Status:	Passed	West Midlands
		B64 5EB

Key for points in following sections:

P	Pass
F	Fail
--	Could not be checked
N/A	Not applicable

Please note: Right = Off side (O/S) and Left = Near side (N/S) as viewed from the driver's seat.

General Information:

Registration:	PN61HHK	Mileage at start of inspection:	30450
Make:	Ford	Model:	Fiesta
Lighting:	Workshop	Colour:	Red
Weather:	Dull and damp	V.I.N:	WFOJXXGAJJBS39709
Ramp available:	Yes		

Body Exterior Fittings:

Window & screen glass:	P	Door locks/operation:	P
Bonnet hinges:	P	Fuel filler cover/cap:	P
Bonnet catch:	P	Number plates:	P
Sunroof operation:	P	Convertible roof operation:	N/A

Interior Fittings:

Seat adjustment:	P	Seatbelts:	P
Boot/tailgate lock:	P	Internal mirrors:	P

Engine Compartment:

Coolant level/condition:	P	Brake fluid:	P
Coolant leaks:	No	Engine oil level:	P
Antifreeze:	P	Oil Leaking:	No
Radiator cap:	P	Engine mountings:	P
Hoses pipes:	P	Cold starting:	P
Auxiliary drive belts:	P	Fast idle (cold):	P
Fuel pump/pipes:	P	Noise level (cold):	P
Power steering oil level:	P	Excess fumes/smoke:	No
Clutch fluid:	P	Turbo/supercharger noisy/leaks:	No

Electrical & Controls:

Starting system/ignition lock:	P	Reverse/fog lights:	P
Battery condition:	P	Auxiliary lights:	P
Battery voltages:	P	Interior/panel lights:	P
- Normal: 12.1	P	Controls/switches:	P
- Starting: 10.5	P	Instruments:	P
- Charging: 13.9	P	Horn:	P
Headlights:	P	Windows/sun roof:	P
Sidelights/running lights:	P	Wipers/washers:	P
Rear & number plate lights:	P	Headlamp wash/wipe:	P
Stop lights:	P	Indicator/hazard lights:	P
Air Con operation:	P		

Front Suspension, Steering & Underframe:

Engine underside leakage:	No	Pipes/hoses:	P
Steering & ball joints:	P	Dampers (condition/leaks):	P
Steering rack/box:	P	Gaiters:	P
Chassis members:	P	Sub-frames/mountings:	P
Power steering (operation):	P	Suspension arms/mountings:	P
Wheel hubs/bearings:	P	Tie bars/anti roll bars:	P
Springs/suspension units:	P		

Rear Suspension & Underframe:

Springs/suspension bars:	P	Bump stops/gaiters:	P
Anti roll bar:	P	Wheel hubs/bearings:	P
Dampers/bushes:	P	Pipes/hoses:	P
Suspension arms/fixings:	P	Sub-frames/mountings:	P
Location rods/fixings:	P	Chassis members:	P

Transmission:

Fluid/oil leaks:	No	Drive shaft assembly:	P
Cables/adjustments:	P	Universal/sliding joints:	P
Hydraulic system:	P	Backlash:	P
Linkage (wear):	P	Gaiters:	P
Casings:	P	Propshaft(s)/fittings:	N/A
Mountings:	P	Bearings/supports:	N/A

Exhaust System:

Manifold:	P	Silencer(s):	P
Pipes:	P	Heat shields/mountings:	P
Catalytic converter(s):	P	Joints/couplings:	P

Fuel System:

Tank:	P	Breather pipes:	P
Tank fixings:	P	Evidence of leaks:	No
Fuel lines:	P		

Brakes:

Master cylinder security:	P	Discs/pads (if visible):	P
Fluid leaks:	No	Handbrake operation:	P
Servo/power system:	P	Flexible hoses:	P
Pedal & pad/linkage:	P	Pipes/connections:	P

Wheels & Tyres:

Wheel rims:	P		
Tyres:	mm		
Front RH:	6.4	P	
Front LH:	6.1	P	
Rear LH:	6.5	P	
Rear RH:	6.9	P	
Spare:	6.9	P	

Road Test:

Test distance:	3 miles
Speed achieved up to:	30 mph

Final drive operation/noise:	P	Steering effort:	P
Gearbox operation/noise level:	P	Hot restarting:	P
Engine performance:	P	Auto changes/kick-down:	N/A
Engine noise:	P	Road holding/stability:	P
Excess smoke:	No	General steering/handling:	P
Overheating evidence:	No	Footbrake operation:	P
Instrument/control function:	P	Hand/park brake operation:	P
Clutch operation:	P	Suspension noise:	No
Cooling fan operation:	P	Warning lights:	P

Rectification Required:

None.

Engineers Comments:

Some components may not have been visible because they were obscured by covers/shields or other equipment.

The AA Mechanical Check service can only describe and/or identify defects actually found and/or which are reasonably capable of being found upon an external visual consideration of the vehicle at the time of the check. We cannot be held and are not responsible for any latent defects which are later discovered.

Engineer: Peter Mackay AMIMI